

August 29, 2014

Mr. Brian Moore
Project Navigator, Ltd.
10497 Town & Country Way, Suite 830
Houston, TX 77024

Dear Brian,

RE: 2014 Workover & Mechanical Integrity Test Report
Malone Service Superfund Site
Plant Injection Well No. 2 (WDW-138)

Please find enclosed six copies of the report on the recent workover and mechanical integrity testing operations on the subject well.

Sandia Technologies, LLC appreciates the opportunity to provide this service for Project Navigator. If you have any questions or concerns regarding this report, please contact me at (832) 286-0471.

Sincerely,

T. Michael Grant, PG
Sr. Wellsite Supervisor

Enclosures (6)